


170913_5.JPG: RMS320-343300, internal view 1 (radar module removed)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 1 of 16






170913_6.JPG: RMS320-343300, internal view 2 (radar module removed)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 2 of 16





170913_8.JPG: RMS320-343300, internal view 3 (radar module and PCB 1 removed)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 3 of 16





170913_15.JPG: RMS320-343300, PCB 1, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 4 of 16






170913_16.JPG: RMS320-343300, PCB 1, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 5 of 16






170913_17.JPG: RMS320-343300, PCB 2, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 6 of 16






170913_18.JPG: RMS320-343300, PCB 2, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 7 of 16






170913_19.JPG: RMS320-343300, PCB 3, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 8 of 16






170913_20.JPG: RMS320-343300, PCB 3, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 9 of 16






170913_12.JPG: RMS320-343300, radar module, front housing removed

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913

 page 10 of 16






170913_13.JPG: RMS320-343300, radar module, internal view 1

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 11 of 16






170913_14.JPG: RMS320-343300, radar module, internal view 2

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 12 of 16






170913_21.JPG: RMS320-343300, radar module, RF-PCB, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 13 of 16





170913_22.JPG: RMS320-343300, radar module, RF-PCB, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 14 of 16






170913_24.JPG: RMS320-343300, radar module, PCB 2, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913

 page 15 of 16





170913_23.JPG: RMS320-343300, radar module, PCB 2, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F170913E2

 Date of issue:
 05/12/2017
 Order Number:
 17-110913
 page 16 of 16