



131992\_c.JPG: RFU620-10101, internal view 1 (cover removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 1 of 15





131992\_i.JPG: RFU620-10101, internal view 2

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 2 of 15






131992\_g.JPG: RFU620-10101, EK-System PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 3 of 15





131992\_h.JPG: RFU620-10101, EK-System PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 4 of 15



page 5 of 15

### **ANNEX C: INTERNAL PHOTOGRAPHS**



131992\_m.JPG: RFU620-10101, EK-Koppler PCB, top view


 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992



page 6 of 15

## **ANNEX C: INTERNAL PHOTOGRAPHS**




131992\_e.JPG: RFU620-10101, EK-Koppler PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992





131992\_j.JPG: RFU620-10101, LPL-Antenne PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 7 of 15





131992\_k.JPG: RFU620-10101, LPL-Antenne PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 8 of 15





131991\_c.JPG: RFU620-10501, internal view 1 (cover removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 9 of 15






131991\_d.JPG: RFU620-10501, internal view 2

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 10 of 15





131991\_e.JPG: RFU620-10501, EK-System PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 11 of 15





131991\_f.JPG: RFU620-10501, EK-System PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 12 of 15





131991\_h.JPG: RFU620-10501, EK-Koppler PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 13 of 15






131991\_i.JPG: RFU620-10501, EK-Koppler PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 14 of 15





131991\_g.JPG: RFU620-10501, LPL-Antenne PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F131992E1

 Date of issue:
 05 June 2013
 Order No.:
 13-111991 and 13-111992
 page 15 of 15