




181673_8.jpg: RFU610-10601, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F181673E4

 Date of issue:
 18.03.2019
 Order Number:
 18-111673
 page 1 of 5






181673_14.jpg: RFU610-10601, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F181673E4

 Date of issue:
 18.03.2019
 Order Number:
 18-111673

 page 2 of 5
 18-111673
 18-111673





181673_13.jpg: RFU610-10601, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F181673E4

 Date of issue:
 18.03.2019
 Order Number:
 18-111673

 page 3 of 5
 page 3 of 5






181673_18.jpg: RFU610-10601, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Report Number:
 F181673E4

 Date of issue:
 18.03.2019
 Order Number:
 18-111673
 page 4 of 5





181673_20.jpg: RFU610-10601, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F181673E4

 Date of issue:
 18.03.2019
 Order Number:
 18-111673

 page 5 of 5
 18-111673
 18-111673