




135012_a.JPG: RFU630, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 1 of 6






135012_b.JPG: RFU630, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 2 of 6





135012_c.JPG: RFU630, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 3 of 6





135012_d.JPG: RFU630, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 4 of 6






135012_e.JPG: RFU630, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 5 of 6





135012_j.JPG: RFU630, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 6 of 6