




152541\_112.JPG: RFU650-10101, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541
 page 1 of 8





152541\_104.JPG: RFU650-10101, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 2 of 8






152541\_102.JPG: RFU650-10101, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 3 of 8





152541\_111.JPG: RFU650-10101, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 4 of 8





152541\_101.JPG: RFU650-10101, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 5 of 8






152541\_105.JPG: RFU650-10101, test set-up open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 6 of 8






152541\_113.JPG: RFU650-10101, test set-up conducted measurements

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541

 page 7 of 8





152541\_107.JPG: RFU650-10101, test set-up shielded room

 Test engineer:
 Thomas KÜHN
 Report Number:
 F152541E3

 Date of issue:
 09/10/2015
 Order Number:
 15-112541
 page 8 of 8