



113961_15.JPG: RFU630, internal view 1

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 1 of 10





113961_16.JPG: RFU630, internal view 2

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 2 of 10






113961_22.JPG: RFU630, internal view 3

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 3 of 10






113961_23.JPG: RFU630, internal view 4

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 4 of 10






113961_19.JPG: RFU630, PCB 1, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 5 of 10






113961_18.JPG: RFU630, PCB 1, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 6 of 10





113961_20.JPG: RFU630, PCB 2, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 7 of 10






113961_21.JPG: RFU630, PCB 2, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 8 of 10






113961_24.JPG: RFU630, PCB 3, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961
 page 9 of 10





113961_25.JPG: RFU630, PCB 3, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113961E2

 Date of issue:
 06 December 2011
 Order No.:
 11-113961

page 10 of 10