



135012\_5.JPG: RFU630, internal view 1

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 1 of 9






135012\_13.JPG: RFU630, internal view 2

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 2 of 9





135012\_14.JPG: RFU630, internal view 3 (antenna removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 3 of 9






135012\_7.JPG: RFU630 PCB 1, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 4 of 9






135012\_8.JPG: RFU630, PCB 1 bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 5 of 9






135012\_11.JPG: RFU630 PCB 2, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 6 of 9






135012\_10.JPG: RFU630, PCB 2 bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 7 of 9






135012\_15.JPG: RFU630 PCB 3, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 8 of 9





135012\_12.JPG: RFU630, PCB 3, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F135012E1

 Date of issue:
 04 November 2013
 Order No.:
 13-115012
 page 9 of 9