



Report No. : FG931114


Appendix B. Setup Photographs

<Radiated Emission>

GSM Link Mode



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G


: B1 of B4 Page Number Report Issued Date: Mar. 30, 2009 Report Version : Rev. 01





Report No.: FG931114

Remote View (Below 1GHz)





Remote View (Above 1GHz)

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B2 of B4
Report Issued Date : Mar. 30, 2009
Report Version : Rev. 01






Report No.: FG931114

Co-location with BT Mode



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B3 of B4
Report Issued Date : Mar. 30, 2009
Report Version : Rev. 01





Report No.: FG931114

Remote View (Below 1GHz)





Remote View (Above 1GHz)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B4 of B4
Report Issued Date : Mar. 30, 2009
Report Version : Rev. 01