

Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : D1 of D2
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01

Report No. : FA162404



FCC SAR Test Report





Report No.: FA162404



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : D2 of D2
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01



Report No.: FA162404

Appendix E. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : E1 of E1
Report Issued Date : Aug. 25, 2011

Report Version : Rev. 01