



Report No.: FR952506

Appendix B. Setup Photographs

<Conducted Emission> Mode 1



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO410G Page Number : B1 of B4
Report Issued Date : Jul. 11, 2009
Report Version : Rev. 01





Report No.: FR952506



Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO410G Page Number : B2 of B4
Report Issued Date : Jul. 11, 2009
Report Version : Rev. 01






Report No.: FR952506

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO410G Page Number : B3 of B4
Report Issued Date : Jul. 11, 2009
Report Version : Rev. 01





Report No. : FR952506



Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO410G Page Number : B4 of B4
Report Issued Date : Jul. 11, 2009
Report Version : Rev. 01