




161191\_05.jpg: Side view 1 of the EUT

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016 Report Number: F161191E1 Order Number: 16-111191 page 1 of 7





161191\_06.jpg: Side view 2 of the EUT

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016 Report Number: F161191E1 Order Number: 16-111191 page 2 of 7





161191\_07.jpg: Side view 3 of the EUT

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 3 of 7






161191\_08.jpg: Side view 4 of the EUT

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 4 of 7





161191\_09.jpg: Top view of the EUT without antenna

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016

Report Number: F161191E1 Order Number: 16-111191





161191\_10.jpg: Bottom view of the EUT

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016 Report Number: F161191E1 Order Number: 16-111191





161191\_11.jpg: Bottom view of the EUT, permanent magnet removed

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016

Report Number: F161191E1 Order Number: 16-111191