



page 1 of 10

### ANNEX C **INTERNAL PHOTOS**



Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016 Report Number: F161191E1 Order Number: 16-111191





161191\_13.jpg: EUT, cabinet opened, battery and antenna cable


 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 2 of 10



page 3 of 10

## ANNEX C INTERNAL PHOTOS




161191\_14.jpg: EUT, cabinet opened, PCB 1

Report Number: F161191E1 Order Number: 16-111191

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016






161191\_15.jpg: PCB 1, top view

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 4 of 10






161191\_16.jpg: PCB 1 without shielding, top view

Test engineer: Wolfgang KASALOWSKY Date of issue: 28.10.2016 Report Number: F161191E1 Order Number: 16-111191





161191\_17.jpg: PCB 1, bottom view

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 6 of 10






161191\_18.jpg: EUT, PCB 1 removed

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 7 of 10






161191\_19.jpg: PCB 2, top view

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 8 of 10





161191\_20.jpg: PCB 2, bottom view

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 9 of 10





161191\_21.jpg: EUT, PCB 1 and PCB 2 removed

 Test engineer:
 Wolfgang KASALOWSKY
 Report Number:
 F161191E1

 Date of issue:
 28.10.2016
 Order Number:
 16-111191
 page 10 of 10