

Report No. : FA231611

Appendix D. Product Photos









TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : D1 of D1
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01



Report No. : FA231611

Appendix E. Test Setup Photos






Right Cheek















Front of the DUT with Earphone to phantom 1 cm gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : E1 of E2
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01





Back of the DUT with phantom 1 cm gap



Report No. : FA231611

Back of the DUT with Earphone to phantom 1 cm gap



Top Side of the DUT with phantom 1 cm gap



Bottom Side of the DUT with phantom 1 cm gap



Right Side of the DUT with phantom 1 cm gap



Left Side of the DUT with phantom 1 cm gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710

Page Number : E2 of E2 Report Issued Date: Apr. 27, 2012 Report Version : Rev. 01