## **Internal Photograph of EUT** 3.

Brand Name: Avvio ; Model Name: Avvio 792S/Avvio 792

Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : 12 of 43 Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01



Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : 13 of 43 Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01



Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 14 of 43 Page Number Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01



Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 15 of 43 Page Number Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01




Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 16 of 43 Page Number Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 17 of 43
Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01




Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 18 of 43 Page Number Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 19 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01



Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 20 of 43 Page Number Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01




Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X Page Number : 21 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755- 3320-2398 FCC ID: WVBA792X Page Number : 22 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01

Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X Page Number : 23 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : 24 of 43 Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01


Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 25 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01


Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 26 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 27 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01




Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 28 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WVBA792X Page Number : 29 of 43
Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01



Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 30 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01



Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 31 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01



Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : 32 of 43 Report Issued Date : Sep. 16, 2013

: Rev. 01 Report Version

Report No.: EP381602




TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 33 of 43
Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01



Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X Page Number : 34 of 43
Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01

Report No.: EP381602






TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : 35 of 43 Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01



Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X Page Number : 36 of 43
Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01




Brand Name: Avvio; Model Name: Avvio 792S/Avvio 792

Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X Page Number : 37 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : 38 of 43 Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01


Report No.: EP381602



TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 39 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755- 3320-2398 FCC ID: WVBA792X

Page Number : 40 of 43
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01




Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 41 of 43 Page Number Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01

Report No.: EP381602




TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 42 of 43 Page Number Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01



Report No.: EP381602



TEL: 86-755-3320-2398 FCC ID: WVBA792X

: 43 of 43 Page Number Report Issued Date : Sep. 16, 2013 Report Version : Rev. 01