3. Internal Photograph of EUT


Brand Name: Avvio; Model Name: Avvio 785S/Avvio 785

Report No.: EP381604



TEL: 86-755- 3320-2398 FCC ID: WVBA785X


Page Number : 12 of 39
Report Issued Date : Sep. 13, 2013





TEL: 86-755-3320-2398 FCC ID: WVBA785X Page Number : 13 of 39


Report Issued Date : Sep. 13, 2013



TEL: 86-755- 3320-2398 FCC ID: WVBA785X

Page Number : 14 of 39
Report Issued Date : Sep. 13, 2013


Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 15 of 39

Report Issued Date: Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 16 of 39
Report Issued Date : Sep. 13, 2013



TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 17 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 18 of 39
Report Issued Date : Sep. 13, 2013

: Rev. 01

Report Version


Report No.: EP381604



TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 19 of 39 Report Issued Date : Sep. 13, 2013




Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 20 of 39

Report Issued Date : Sep. 13, 2013









TEL: 86-755- 3320-2398 FCC ID: WVBA785X Page Number : 21 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 22 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 23 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604



TEL: 86-755- 3320-2398 FCC ID: WVBA785X Page Number : 24 of 39
Report Issued Date : Sep. 13, 2013

Brand Name: Avvio; Model Name: Avvio 785S/Avvio 785



TEL: 86-755-3320-2398 FCC ID: WVBA785X Page Number : 25 of 39
Report Issued Date : Sep. 13, 2013

: Rev. 01

Report Version

Report No.: EP381604




TEL: 86-755- 3320-2398 FCC ID: WVBA785X Page Number : 26 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 27 of 39
Report Issued Date : Sep. 13, 2013



TEL: 86-755- 3320-2398 FCC ID: WVBA785X


Page Number : 28 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 29 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604



TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 30 of 39
Report Issued Date : Sep. 13, 2013




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 31 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 32 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604



TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 33 of 39
Report Issued Date : Sep. 13, 2013

Report No.: EP381604




TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 34 of 39
Report Issued Date : Sep. 13, 2013

: Rev. 01

Report Version




Brand Name: Avvio; Model Name: Avvio 785S/Avvio 785



TEL: 86-755-3320-2398 FCC ID: WVBA785X


Page Number : 35 of 39 Report Issued Date: Sep. 13, 2013

Report No.: EP381604



TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 36 of 39
Report Issued Date : Sep. 13, 2013


Report No.: EP381604



TEL : 86-755- 3320-2398 FCC ID : WVBA785X Page Number : 37 of 39
Report Issued Date : Sep. 13, 2013



Report No.: EP381604




TEL: 86-755-3320-2398 FCC ID: WVBA785X

Page Number : 38 of 39 Report Issued Date: Sep. 13, 2013



Report No.: EP381604



TEL: 86-755- 3320-2398 FCC ID: WVBA785X Page Number : 39 of 39 Report Issued Date : Sep. 13, 2013