Test report No. : 10133943H-A-R2

Page : 54 of 56

: December 18, 2013 **Issued date** : February 26, 2014 : WY7-21

Revised date FCC ID

# **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**




Photo 1




Photo 2

# UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10133943H-A-R2

Page : 55 of 56

: December 18, 2013 **Issued date** : February 26, 2014 : WY7-21

Revised date FCC ID

# **Radiated Spurious Emission**



Photo 1




Photo 2

# UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10133943H-A-R2


Page : 56 of 56

Issued date : December 18, 2013 Revised date : February 26, 2014


FCC ID : WY7-21

# Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)


#### X-axis



Y-axis



**Z**-axis



### **End of Report**

## UL Japan, Inc.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124