



Spurious emissions from the receiver (receive on 156.025 MHz and 162.025 MHz):

190015_112.wmf: Spurious emissions from the receiver (9 kHz to 150 kHz):



Remark: The emission on 70 kHz is caused by the measuring system and not by the EUT 190015_113.wmf: Spurious emissions from the receiver (150 kHz to 30 MHz):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1


 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 1 of 8



190015 114.wmf: Spurious emissions from the receiver (30 MHz to 1 GHz):



190015 115.wmf: Spurious emissions from the receiver (1 GHz to 4 GHz):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 2 of 8




Spurious emissions from the transmitter (transmit on 156.025 MHz):

190015_106.wmf: Spurious emissions from the transmitter (9 kHz to 150 kHz):



Remark: The emission on 70 kHz is caused by the measuring system and not by the EUT

190015 107.wmf: Spurious emissions from the transmitter (150 kHz to 30 MHz):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015


 page 3 of 8



190015 108.wmf: Spurious emissions from the transmitter (30 MHz to 200 MHz, carrier notched):



190015 109.wmf: Spurious emissions from the transmitter around the carrier (carrier notched):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1


 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 4 of 8



190015 110.wmf: Spurious emissions from the transmitter (200 MHz to 1 GHz):



190015 111.wmf: Spurious emissions from the transmitter (1 GHz to 4 GHz):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 5 of 8




Spurious emissions from the transmitter (transmit on 162.025 MHz):

190015_104.wmf: Spurious emissions from the transmitter (9 kHz to 150 kHz):



Remark: The emission on 70 kHz is caused by the measuring system and not by the EUT

190015 105.wmf: Spurious emissions from the transmitter (150 kHz to 30 MHz):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1


 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 6 of 8



190015 100.wmf: Spurious emissions from the transmitter (30 MHz to 200 MHz ,carrier notched):



190015 101.wmf: Spurious emissions from the transmitter (carrier notched):




 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1


 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 7 of 8



190015 102.wmf: Spurious emissions from the transmitter (200 MHz to 1000 MHz):



190015 103.wmf: Spurious emissions from the transmitter (1 GHz to 4 GHz):



 Test engineer:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015
 page 8 of 8