


190015_5.jpg: CAMINO-108S, internal view 1

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 8 of 17




190015_6.jpg: CAMINO-108S, internal view 2 (RF connetions opened)

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 9 of 17
 page 9 of 17




190015_7.jpg: CAMINO-108S, internal view 3 (PCB 1 removed)

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

page 10 of 17




190015_8.jpg: CAMINO-108S, internal view 4 (shielding removed)

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

page 11 of 17




190015_11.jpg: CAMINO-108S, PCB 1, top view

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 12 of 17
 page 12 of 17



190015_12.jpg: CAMINO-108S, PCB 1, bottom view

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 13 of 17
 page 13 of 17



190015_10.jpg: CAMINO-108S, PCB 2, top view

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 14 of 17
 page 14 of 17



190015_9.jpg: CAMINO-108S, PCB 1, bottom view

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 15 of 17
 page 15 of 17




190015_13.jpg: CAMINO-108S, PCB 1, top view

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 16 of 17
 page 16 of 17



190015_14.jpg: CAMINO-108S, PCB 1, bottom view

 Examiner:
 Thomas KÜHN
 Report Number:
 F190015E1

 Date of issue:
 23.07.2019
 Order Number:
 19-110015

 page 17 of 17
 page 17 of 17