Test report No. : 12069761H-A-R1
Page : 45 of 46
Issued date : October 16, 2018
FCC ID : X4QKDTG105

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12069761H-A-R1
Page : 46 of 46
Issued date : October 16, 2018
FCC ID : X4QKDTG105

Worst Case Position

Below 1 GHz (Horizontal: Y-axis/ Vertical: X-axis)
Above 1 GHz (Horizontal: Z-axis/ Vertical: Y-axis)
Second harmonic wave (Horizontal: Y-axis/ Vertical: X-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124