



161297LFC\_emi1

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 1 of 7






161297LFC\_emi2

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 2 of 7





161297LFC\_emi1mag

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 3 of 7





161297LFC\_emi2mag

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 4 of 7





161297LFC\_emi3mag

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 5 of 7





161297LFC\_pos1


Test engineer: Michael DINTER Report Number: F161297E2
Date of issue: 07.02.2017 Order Number: 16-111297

page 6 of 7



page 7 of 7

Annex A Test setup photos



161297LFC\_pos2

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297