


161065\_1b.jpg: BT7000, test setup fully anechoic chamber (position 1)

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065
 page 1 of 7






161065\_1a.jpg: BT7000, test setup fully anechoic chamber (position 2)

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 2 of 7
 page 2 of 7






161065\_1c.jpg: BT7000, test setup fully anechoic chamber (position 3)

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065
 page 3 of 7






161065\_1d.jpg: BT7000, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 4 of 7
 page 4 of 7





161065\_1e.jpg: BT7000, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 5 of 7
 page 5 of 7






161065\_1g.jpg: BT7000, test setup outdoor test site

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 6 of 7
 page 6 of 7





161065\_1i.jpg: BT7000, test setup open area test site

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 7 of 7
 page 7 of 7