




161065_105.jpg: BT7000, internal view

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 1 of 4
 16-111065
 16-111065






161065_106.jpg: BT7000, PCB, top view

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 2 of 4





161065_107.jpg: BT7000, PCB, bottom view

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 3 of 4





161065_108.jpg: BT7000, PCB, bottom view, Bluetooth module removed

 Examiner:
 Thomas KÜHN
 Report Number:
 F161065E2

 Date of issue:
 07/15/2016
 Order Number:
 16-111065

 page 4 of 4