



151497_n_16.JPG: FPS COM 7000, internal view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497
 page 1 of 8






151497_n_3.JPG: FPS COM 7000, PCB2, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 2 of 8






151497_n_8.JPG: FPS COM 7000, PCB2, top view, antenna removed

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497
 page 3 of 8






151497_n_9.JPG: FPS COM 7000, PCB2, top view, antenna and shielding removed

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 4 of 8






151497_n_12.JPG: FPS COM 7000, PCB2, top view, unspotted sample (supplied by the applicant)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 5 of 8






151497_n_4.JPG: FPS COM 7000, PCB2, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497
 page 6 of 8






151497_n_10.JPG: FPS COM 7000, additional PCBs, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 7 of 8





151497_n_11.JPG: FPS COM 7000, additional PCBs, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E9

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 8 of 8