


161297LFC330_eut1

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 1 of 5






161297LFC330_eut2

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 2 of 5





161297LFC330_eut3

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 3 of 5






161297LFCBT_eut1

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 4 of 5





161297LFCBT_eut2

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 5 of 5