


161297LFCBT_eut3

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 1 of 7





161297LFCBT_eut4

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 2 of 7






161297LFCBT_eut5

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 3 of 7






161297LFCBT_eut6

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 4 of 7





161297LFCBT_eut7

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 5 of 7






161297LFCBT_eut8

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 6 of 7





161297LFCBT_eut8a

 Test engineer:
 Michael DINTER
 Report Number:
 F161297E2

 Date of issue:
 07.02.2017
 Order Number:
 16-111297
 page 7 of 7