


Report No.: FA020335A

Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : D1 of D2
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01



Report No.: FA020335A

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : D2 of D2
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01




Report No.: FA020335A

Appendix E. **Test Setup Photos**



Right Cheek


Right Tilted







Left Tilted



Face of the DUT with Phantom 1.5 cm Gap (DUT with Earphone 1)



Bottom of the DUT with Phantom 1.5 cm Gap (DUT with Earphone 1)


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800

: E1 of E2 Page Number Report Issued Date: Apr. 21, 2010 Report Version : Rev. 01



FCC SAR Test Report



Face of the DUT with Phantom 1.5 cm Gap (DUT with Earphone 2)

Bottom of the DUT with Phantom 1.5 cm Gap (DUT with Earphone 2)

Report No.: FA020335A

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : E2 of E2
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01