

Report No.: FR611201-01E

Appendix C. Setup Photographs

<Conducted Emission> Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS

: C1 of C4 Page Number Report Issued Date: Apr. 27, 2016 : Rev. 01 Report Version




Report No. : FR611201-01E


<Radiated Emission>

Z Plane For WLAN5GHz 802.11a

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C2 of C4
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01




Report No. : FR611201-01E

X Plane For WLAN5GHz 802.11n HT20/HT40/WLAN5GHz 802.11ac VHT40/VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C3 of C4
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01




Report No.: FR611201-01E

X Plane For WLAN5GHz 802.11ac VHT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C4 of C4
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01