

### Appendix C. Setup Photographs

# <Conducted Emission> Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C1 of C4
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC Version 1.3

Report No.: FR611201-01D




## Report No.: FR611201-01D


#### <Radiated Emission>

#### Z Plane For WLAN5GHz 802.11a

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS


Page Number : C2 of C4 Report Issued Date: Apr. 27, 2016 Report Version : Rev. 01

Report Template No.: BU5-FR15EWLAC Version 1.3




X Plane For WLAN5GHz 802.11n HT20/HT40/WLAN5GHz 802.11ac VHT40/VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C3 of C4
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report No.: FR611201-01D


Report Template No.: BU5-FR15EWLAC Version 1.3




Report No.: FR611201-01D

#### X Plane For WLAN5GHz 802.11ac VHT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS

Page Number : C4 of C4 Report Issued Date: Apr. 27, 2016 Report Version : Rev. 01

Report Template No.: BU5-FR15EWLAC Version 1.3