During assessment, the transmitter laying flat on the table was found to be the position where the greatest RF levels were measured, and is pictured in the photos on the following pages. See the report for full details.





