Test report No. : 11891919H-R1 Page : 26 of 28

Issued date : November 17, 2017 FCC ID : Y8PFJ18-1

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 11891919H-R1 Test report No. : 27 of 28 Page

Issued date : November 17, 2017 : Y8PFJ18-1 FCC ID

Worst Case Position

Antenna (Type 1)

Below 30 MHz X-axis

Above 30 MHz Horizontal: X-axis / Vertical: X-axis

X-axis

Antenna (Type 2) Below 30 MHz X-axis Above 30 MHz

Horizontal: X-axis / Vertical: X-axis

X-axis




Y-axis



Z-axis






Y-axis



Z-axis



UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11891919H-R1 Page : 28 of 28

Issued date : November 17, 2017 FCC ID : Y8PFJ18-1

Worst Case Position


ECU Below 30 MHz X-axis Above 30 MHz

Horizontal: X-axis / Vertical: X-axis





Y-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124