Test report No.
 : 12047157H-A-R1

 Page
 : 27 of 29

 Issued date
 : April 5, 2018

 FCC ID
 : Y8PFJ18-2

## **APPENDIX 3: Photographs of test setup**

# **Radiated Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12047157H-A-R1 : 28 of 29 Page **Issued date** : April 5, 2018 : Y8PFJ18-2 FCC ID

## **Worst Case Position**

Antenna (Type 1) Below 30 MHz X-axis Above 30 MHz

Horizontal: X-axis / Vertical: X-axis

X-axis

Antenna (Type 2) Below 30 MHz X-axis Above 30 MHz Horizontal: X-axis / Vertical: X-axis


X-axis
















#### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12047157H-A-R1
Page : 29 of 29
Issued date : April 5, 2018
FCC ID : Y8PFJ18-2


# **Worst Case Position**


ECU Below 30 MHz X-axis Above 30 MHz

Horizontal: X-axis / Vertical: X-axis









**End of Report** 

### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124