Test report No. : 10893288H-R1
Page : 16 of 18

Issued date : September 18, 2015 Revised date : November 16, 2015 FCC ID : Y8PFJ16-2

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 10893288H-R1 Test report No. : 17 of 18 Page


Issued date : September 18, 2015 : November 16, 2015 Revised date FCC ID : Y8PFJ16-2

Worst Case Position

Antenna Below 30MHz: Z Above 30MHz: Horizontal X, Vertical X












Joint Box Below 30MHz: X Above 30MHz: Horizontal Y, Vertical Y







UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 : +81 596 24 8124 Facsimile

Test report No. : 10893288H-R1 Page : 18 of 18

Issued date : September 18, 2015 Revised date : November 16, 2015 FCC ID : Y8PFJ16-2

Worst Case Position



With key (Worst)



Without key

End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124