Test report No. : 12812711H-A-R2
Page : 29 of 31
Issued date : June 25, 2019
FCC ID : Y8PSU19S-1

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 12812711H-A-R2
Page : 30 of 31
Issued date : June 25, 2019
FCC ID : Y8PSU19S-1


Worst Case Position

Antenna (TYPE 1) Below 30MHz: X


Above 30MHz: Horizontal X, Vertical X
X-axis









Antenna (TYPE 2) Below 30MHz: X Above 30MHz: Horizontal X, Vertical X X-axis







UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12812711H-A-R2
Page : 31 of 31
Issued date : June 25, 2019
FCC ID : Y8PSU19S-1

Worst Case Position

Smart ECU Below 30MHz: X

Above 30MHz: Horizontal X, Vertical X







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124