



802 N. Twin Oaks Valley Rd., Suite 105

San Marcos, CA 92069

Phone: (760) 471-2100

FAX: (760) 471-2121

www.rfexposurelab.com

American Certification Body 6731 Whittier Avenue, Suite C110 McLean, VA 22101 USA

Ref: Change for FCC ID Y99MC7354 dated October 5, 2015

I would like to have the above mentioned FCC grant exhibits changed. The device does require simultaneous evaluation which was not done for the filing. A revised SAR report has been issued which evaluates the simultaneous requirements of KDB 447498. Further, the correspondence which was loaded indicating the device had redundancy only needs to be removed from the filing.

The product has not been marketed or sold anywhere under this ID.

If you have any questions, please contact me at the below information.

Thank you,

RF Exposure Lab,

802 N. Twin Oaks Valley Road, Suite 105

San Marcos, CA 92069 Ph: (760) 471-2100

Fax: (760) 471-2121

Email: jmmoulton@rfexposurelab.com