



# Appendix B. Setup Photographs

<Radiated Emission>
<CDMA2000 BC0 with DC 12V>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1303 Page Number : B1 of B4
Report Issued Date : May 30, 2013
Report Version : Rev. 01


Report No.: FG343002-01




Report No.: FG343002-01

## <CDMA2000 BC0 with DC 24V>

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1303 Page Number : B2 of B4
Report Issued Date : May 30, 2013
Report Version : Rev. 01




Report No.: FG343002-01

## <CDMA2000 BC1 with DC 12V>

LF



## HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1303 Page Number : B3 of B4
Report Issued Date : May 30, 2013
Report Version : Rev. 01




Report No.: FG343002-01

## <CDMA2000 BC1 with DC 24V>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1303 Page Number : B4 of B4
Report Issued Date : May 30, 2013
Report Version : Rev. 01