


Appendix B. Setup Photographs

<Radiated Emission>


<X Plane>

DC 12V

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1304 Page Number : B1 of B4
Report Issued Date : Jun. 11, 2013
Report Version : Rev. 01


Report No.: FG343001




Report No. : FG343001

DC 24V

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1304 Page Number : B2 of B4
Report Issued Date : Jun. 11, 2013
Report Version : Rev. 01




Report No. : FG343001


<Y Plane>

DC 12V

LF



HF




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1304 Page Number : B3 of B4
Report Issued Date : Jun. 11, 2013
Report Version : Rev. 01



Report No.: FG343001

DC 24V

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YA7-ATVT1304 Page Number : B4 of B4
Report Issued Date : Jun. 11, 2013
Report Version : Rev. 01