


162097\_07.jpg: Test setup – antenna port conducted measurements

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097

 page 1 of 7
 page 1 of 7






162097\_01.jpg: Test setup fully anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097

 page 2 of 7
 page 2 of 7






162097\_02.jpg: Test setup fully anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097

 page 3 of 7
 7





162097\_03.jpg: Test setup fully anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097

 page 4 of 7
 7






162097\_05.jpg: Test setup open area test site

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097

 page 5 of 7
 page 5 of 7






162097\_04.jpg: Test setup fully anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097

 page 6 of 7
 7





162097\_06.jpg: Test setup fully anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F162097E1

 Date of issue:
 21.08.2017
 Order Number:
 16-112097