


110734_d.jpg Switch PCB, rear view

Report Number: F110734E2, 2nd versioin Order Number: 110734

Test engineer: Thomas KÜHN Date of issue: 13 April 2012






110734_e.jpg Switch PCB, front view

Test engineer: Thomas KÜHN Report Number: F110734E2, 2nd versioin Date of issue: 13 April 2012 Order Number: 110734

page 2 of 7






110734_l.jpg Switch PCB, rear view, detail view to Bluetooth unit

Report Number: F110734E2, 2nd versioin Order Number: 110734






110734_o.jpg Switch PCB, rear view, detail view to Bluetooth unit, housing removed

Test engineer: Thomas KÜHN Report Number: F110734E2, 2nd versioin Date of issue: 13 April 2012 Order Number: 110734






110734_k.jpg Switch PCB, rear view, detail view to Bluetooth unit (sample with temporary antenna connector)

Test engineer: Thomas KÜHN Report Number: F110734E2, 2nd versioin Date of issue: 13 April 2012 Order Number: 110734

page 5 of 7






110734_n.jpg ALPS evaluation board, top view

Report Number: F110734E2, 2nd versioin Order Number: 110734





110734_m.jpg ALPS evaluation board, bottom view

Test engineer: Thomas KÜHN Report Number: F110734E2, 2nd versioin Date of issue: 13 April 2012 Order Number: 110734

page 7 of 7