

# Appendix D. Setup Photographs

### <Conducted Emission>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D1 of D3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02

Report No.: FR662816B

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2




## Report No. : FR662816B


### <Radiated Emission>

### X Plane for Bluetooth v4.0 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D2 of D3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2




### Z Plane for Bluetooth v4.2 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D3 of D3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02

Report No.: FR662816B

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2