


## Appendix C. Setup Photographs


### <Radiated Emission>

X Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : C1 of C1
Report Issued Date : Dec. 30, 2016
Report Version : Rev. 02
Report Template No.: BU5-FGLTE Version 1.6

Report No.: FG662816-04B

# **Appendix D. Product Equality Declaration**

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D1 of D1
Report Issued Date : Dec. 30, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.6

Report No.: FG662816-04B

## Lenovo Mobile Communication Technology Ltd.

No.999, Qishan North 2nd Road, Information & Optoelectronics Park, Torch Hi-tech Industry Development Zone, Xiamen, P.R.China

Tel: 86-10-58866181; Fax: 86-10-56720293

Date: December 30, 2016

## **Product Equality Declaration**


We, Lenovo Mobile Communication Technology Ltd., declare on our sole responsibility for the product of Lenovo K33b36 (Dual SIMs) &K33b37 (Single SIM) as below:

The differences between Lenovo K33b36 (Dual SIMs) &K33b37 (Single SIM) and previous as below:

### 1. LCD panel changed.

Object	Original	Variant
LCD	Item number code for	Item number code for TL050VVMP04-00
	TL050VVXP14-00	
	Item number code for	Item number code for TL050VVMP06-00
	TL050VVXP16-00	

### 2. This difference is normal difference.



Except listings above, the others are all the same.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely yours,

Contact Person: Li xihong

Xihong Li

COMPANY: Lenovo Mobile Communication Technology Ltd.

Tel: 18910866181 Fax: 86-10-57874529

E-Mail: lixh5@lenovo.com