


Report No. : FA332604


Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YCNK900 Page Number : D1 of D2
Report Issued Date : Apr. 28, 2013
Report Version : Rev. 01







Report No.: FA332604

Front of the DUT with Phantom 1 cm Gap


Back of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YCNK900

Page Number : D2 of D2 Report Issued Date: Apr. 28, 2013

Report Version : Rev. 01