
Internal photographs of equipment under test.





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Bushnell Inc. Model: Speedster III (101921)
Test #: 100615A
Test to: FCC Parts 2 and 15c, RSS-210
File: IntPho Speedster3

FCC ID: YEQ1019210 IC: 5380A-1019210 SN: ENG1

Date: July 22, 2010 Page 1 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Bushnell Inc.

Model: Speedster III (101921)
Test #: 100615A
Test to: FCC Parts 2 and 15c, RSS-210
File: IntPho Speedster3

FCC ID: YEQ1019210 IC: 5380A-1019210 SN: ENG1

Date: July 22, 2010 Page 2 of 4






Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Bushnell Inc.

Model: Speedster III (101921)
Test #: 100615A
Test to: FCC Parts 2 and 15c, RSS-210
File: IntPho Speedster3

FCC ID: YEQ1019210 IC: 5380A-1019210 SN: ENG1 Date: July 22, 2010 Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Bushnell Inc. Model: Speedster III (101921)
Test #: 100615A
Test to: FCC Parts 2 and 15c, RSS-210
File: IntPho Speedster3

FCC ID: YEQ1019210 IC: 5380A-1019210 SN: ENG1

Date: July 22, 2010 Page 4 of 4