


Report No. : FA411002


Appendix D. Test Setup Photos





Right Cheek







Left Cheek


Left Tilted

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FAX: 86-029-8860-8791 FCC ID: YHLBLUSTUD50SII Page Number : D1 of D2 Report Issued Date: Mar. 04, 2014

Report Version : Rev. 01







Report No.: FA411002

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FAX: 86-029-8860-8791 FCC ID: YHLBLUSTUD50SII Page Number : D2 of D2 Report Issued Date: Mar. 04, 2014

Report Version : Rev. 01