

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBET Page Number : D1 of D2
Report Issued Date : Oct. 20, 2011
Report Version : Rev. 01

Report No.: FA082005-04



Report No.: FA082005-04


Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBET Page Number : D2 of D2
Report Issued Date : Oct. 20, 2011
Report Version : Rev. 01




Appendix E. Test Setup Photos




Report No.: FA082005-04

Right Cheek

Right Tilted







Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBET Page Number : E1 of E1
Report Issued Date : Oct. 20, 2011
Report Version : Rev. 01