


Report No.: FA130433A

Appendix D. Product Photos








SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC

Page Number : D1 of D2 Report Issued Date: Apr. 26, 2011 : Rev. 02 Report Version



Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : D2 of D2
Report Issued Date : Apr. 26, 2011
Report Version : Rev. 02

Report No.: FA130433A



Appendix E. Test Setup Photos



Report No.: FA130433A

Right Cheek

Right Tilted







Left Tilted



Front Face of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Front Face of the DUT with Phantom 1 cm Gap (DUT with Earphone)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : E1 of E2
Report Issued Date : Apr. 26, 2011
Report Version : Rev. 02



Rear Face of the DUT with Phantom 1 cm Gap (DUT without Earphone)




Report No.: FA130433A

Rear Face of the DUT with Phantom 1 cm Gap (DUT with Earphone)



Left Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Right Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Bottom Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : E2 of E2
Report Issued Date : Apr. 26, 2011
Report Version : Rev. 02