

Report No.: FA151304

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBARQ Page Number : D1 of D2
Report Issued Date : Jun. 16, 2011
Report Version : Rev. 01



Report No. : FA151304

Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBARQ Page Number : D2 of D2
Report Issued Date : Jun. 16, 2011
Report Version : Rev. 01



Report No.: FA151304

Appendix E. Test Setup Photos





Right Cheek

Right Tilted







Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBARQ Page Number : E1 of E1
Report Issued Date : Jun. 16, 2011
Report Version : Rev. 01