

Report No. : FA141403

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDEEJAYII Page Number : D1 of D2
Report Issued Date : Jun. 03, 2011
Report Version : Rev. 01



Report No. : FA141403

Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDEEJAYII Page Number : D2 of D2
Report Issued Date : Jun. 03, 2011
Report Version : Rev. 01



Report No.: FA141403

Appendix E. Test Setup Photos



Right Cheek







Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDEEJAYII Page Number : E1 of E1
Report Issued Date : Jun. 03, 2011
Report Version : Rev. 01