



Page Number : A42 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A43 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A44 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A45 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A46 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A47 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01



Page Number : A48 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A49 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A50 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01

Conducted Band Edge




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUEGXLTE Page Number : A51 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A52 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A53 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01



Page Number : A54 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A55 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUEGXLTE Page Number : A56 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A57 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A58 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A59 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A60 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A61 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A62 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A63 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A64 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A65 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A66 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01




Page Number : A67 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01



Page Number : A68 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01



Page Number : A69 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01



Page Number : A70 of A109
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01