

Report No.: FA181517

Appendix D. Product Photos



SPORTON INTERNATIONAL (KUNSHAN) INC.

5


6 7 8 9 10 11 12 13

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBJR Page Number : D1 of D2
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01



Report No. : FA181517

Antenna Location:




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBJR Page Number : D2 of D2
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01



Report No.: FA181517

Appendix E. Test Setup Photos



Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBJR Page Number : E1 of E1
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01