

Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : B1 of B3
Report Issued Date : May 12, 2011
Report Version : Rev. 02

Report No.: FD090827-02






Report No.: FD090827-02

<Radiated Emission>

Mode 1 and 4




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : B2 of B3
Report Issued Date : May 12, 2011
Report Version : Rev. 02






Report No.: FD090827-02

Mode 2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : B3 of B3
Report Issued Date : May 12, 2011
Report Version : Rev. 02